


REF. NO.	PART NUMBER	DESCRIPTION	QTY.								
				L1013	L1113	L1116	L1117	L1316	L1317	L1418	LS1418
1	344 750 70 02	Grille (Pre Phase II)	1	■	■	■		■		■	■
2	331 751 00 18	Grille (Phase II)	1		■	■	■	■	■		
3	331 750 00 02	Grille Frame (Phase II)	1		■	■	■	■	■		



Exterior Mirrors/Group 81

REF. NO.	PART NUMBER	DESCRIPTION	QTY.								
				L1013	L1113	L1116	L1117	L1316	L1317	L1418	LS1418
1	900 811 00 30	Mirror Head	1	■	■	■		■		■	■
1	376 810 05 16	Mirror Head/Phase II (From Chassis 619235)	1		■	■		■			
2	900 811 03 14	Bracket/Left and Right	2	■	■	■		■		■	■
3	331 811 00 36	Top Left Bracket	1		■		■		■		
3	331 811 01 36	Top Right Bracket	1		■		■		■		
4	331 811 00 96	Shim Gasket, Upper	2		■		■		■		
5	381 811 03 36	Bottom Left & Right Bracket	2		■		■		■		
6	381 811 05 96	Shim Gasket, Lower	2		■		■		■		
7	976 811 00 30	Mirror Head (From Chassis 643428) <i>3768100716</i>	2		■		■		■		
8	344 810 78 18	Grille Star	1	■	■	■		■		■	■
8	331 810 00 18	Grille Star (Phase II)	1		■	■	■	■	■		
9	314 817 04 16	Hood Emblem	1	■	■	■	■	■	■	■	■
10	344 817 75 14	L1113 (Black) Type Designation <i>30217 0814 Chrome</i>	2		■						

When you consider the cost and nuisance of having to replace a counterfeit part after installation, you can appreciate the real worth of genuine Mercedes-Benz replacement parts.